Supplied with display

Optional accessory

POWER

Red (FUSE)

Black

Yellow

Blue
No Connect

Wake up wire
Used to turn on accessories

10 - 17 V DC

HDS Display



NMEA2000 Devices

LGC-4000 GPS Receiver
Temperature Sensor
Fluid Level Sensor
Fuel Flow Sensor
Pressure Sensor
Heading Sensor/Compass
Engine Interface
SonicHub Audio Server
LMF Gauges
VHF Radio

Power/Data Cable

NMEA0183

RS-422

HDS	Device
Green RX (-)	Transmit (-)
Orange RX (+)	Transmit (+)
Shield (ground)	Ground
Yellow TX (+)	Receive (+)
Blue TX (-)	Receive (-)

RS-232 HDS-8/10 only

	HDS	Device
Com 1	Yellow TX	Receive
	Orange RX	Transmit
	Shield (ground)	Ground

	HDS	Device
Com 2	Blue TX	Receive
	Green RX	Transmit
	Shield (ground)	Ground

NMEA2000



12v

Skimmer transducer included with most HDS



RADAR

BR24 BroadBand Radar





* Radar interface box not included with US version of BR24 Required for MARPA

RC42



Sirius Weather Module LWX-1